

# Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325427

Inspection Document #: 714000439

La Plata County, CO

Township: NESW 7 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Neleigh 01-07 1  
Location ID: 325427



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos  
Location Name: Neleigh 01-07 1  
Location ID: 325427



Photo 2. View of wood pallet debris observed on location.



Inspection Photos  
Location Name: Neleigh 01-07 1  
Location ID: 325427

2/16/24  
+37.227347,-107.680040  
216° SW



**Photo 3.** View of the southern interim reclamation area facing southwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06357

Inspection Photos  
Location Name: Neleigh 01-07 1  
Location ID: 325427



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of rill erosion forming in the northern interim reclamation.

API #: 067-06357

Inspection Photos  
Location Name: Neleigh 01-07 1  
Location ID: 325427



**Photo 5.** View of exposed/loose soil pile stored on the western edge of the disturbance.



Inspection Photos  
Location Name: Neleigh 01-07 1  
Location ID: 325427



2/16/24  
+37.228199,-107.680322  
11° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of the reference area comprise of smooth brome, sagebrush and juniper.

API #: 067-06357