

# Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306769

Inspection Document #: 714000440

La Plata County, CO

Township: SWSE 7 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Neleigh 01-07 2  
Location ID: 306769



Photo 1. View of the disturbance from the entrance facing center.





Inspection Photos  
Location Name: Neleigh 01-07 2  
Location ID: 306769



**Photo 2.** View of the eastern interim reclamation area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08725



Inspection Photos  
Location Name: Neleigh 01-07 2  
Location ID: 306769



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of culvert debris stored in the eastern interim reclamation area.

API #: 067-08725



Inspection Photos  
Location Name: Neleigh 01-07 2  
Location ID: 306769



2/16/24  
+37.225452, -107.674722  
261° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of wattles in the western interim reclamation area that are not longer functioning.

API #: 067-08725



Inspection Photos  
Location Name: Neleigh 01-07 2  
Location ID: 306769



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Produced water sign CA identified in the previous inspection doc  
#712700615 has been addressed/resolved.

API #: 067-08725



Inspection Photos  
Location Name: Neleigh 01-07 2  
Location ID: 306769



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** View of the reference area comprised of smooth brome and juniper.

API #: 067-08725