

# Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306897

Inspection Document #: 714000441

La Plata County, CO

Township: NESW 8 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Gearhart C2  
Location ID: 306897



Photo 1. View of the disturbance from the entrance facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08997

Inspection Photos  
Location Name: Gearhart C2  
Location ID: 306897



**Photo 2.** View of weedy kochia debris piling up in the western edge of the disturbance.

Inspection Photos  
Location Name: Gearhart C2  
Location ID: 306897



**Photo 3.** Chemical container CA identified in previous inspection doc #712700686 has been addressed/resolved. Chemical container is now connected to the well head.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08997

Inspection Photos  
Location Name: Gearhart C2  
Location ID: 306897

2/16/24  
+37.222899,-107.663445  
83° E



**Photo 4.** Reference area is a pasture comprised of dormant grasses.

