

Inspection Photos
Location: Bledsoe Ranch 14-30
Facility ID: 321600



Photo 1 – Well placard



Photo 2 – Wellhead

Inspection Photos
Location: Bledsoe Ranch 14-30
Facility ID: 321600



**Photo 3 – Machine Guarding not maintained.
Electrical Panel and Rectifier**



Photo 4 – Guarding not maintained, Electrical drop

Inspection Photos
Location: Bledsoe Ranch 14-30
Facility ID: 321600



Photo 5 – Location of Former Tank Battery
Approximately, 1,150 feet northeast from well location



Photo 6 – Areas of impacted soils located on the
Historical Tank Battery site

Inspection Photos
Location: Bledsoe Ranch 14-30
Facility ID: 321600



Photo 7 – Areas of impacted soils located on the Historical Tank Battery site



Photo 8 – Areas of impacted soils located on the Historical Tank Battery site

Inspection Photos
Location: Bledsoe Ranch 14-30
Facility ID: 321600



Photo 9 – Areas of impacted soils located on the Historical Tank Battery site



Photo 10 – Areas of impacted soils located on the Historical Tank Battery site