

Inspection Photos
Location: Bledsoe Ranch 12-30 8
Facility ID: 380962



Photo 1 – Tank Battery Placard



Photo 2 – Impacted Soils at Tank Battery

Inspection Photos
Location: Bledsoe Ranch 12-30 8
Facility ID: 380962



Photo 3 – Impacted soils

Photo 4 – Treater


Inspection Photos
Location: Bledsoe Ranch 12-30 8
Facility ID: 380962



Photo 5 – Containment Berm on West side of Tank Battery

Photo 6 – Well Placard at wellhead

Inspection Photos
Location: Bledsoe Ranch 12-30 8
Facility ID: 380962



**Photo 7 – Areas of impacted soils at the wellhead, 5
Gallon buckets stored on location**

Photo 8 – Rear of pumping unit

Inspection Photos
Location: Bledsoe Ranch 12-30 8
Facility ID: 380962



Feb 15, 2024 at 12:20:58 PM
+38-976039-103.049182
ECMC

Photo 9 – 5-gallon bucket and trash at rear of pumping unit



Feb 15, 2024 at 12:21:16 PM
+38-975967-103.049112
ECMC

Photo 10 – Trash and Debris inside of pumping unit frame