

Inspection Photos
Location: Grays-State 33-36 # 1
Facility ID: 321673



Photo 1 –Wellhead Placard

Photo 2 – Wellhead with oil staining

Inspection Photos
Location: Grays-State 33-36 # 1
Facility ID: 321673



Photo 3 – Oil Staining at pumping unit base