

Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306765

Inspection Document #: 714000453

La Plata County, CO

Township: NENW 7 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Holman Canyon 2
Location ID: 306765



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Holman Canyon 2
Location ID: 306765



Photo 2. View of scotch thistle observed in the interim reclamation areas.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08720

Inspection Photos
Location Name: Holman Canyon 2
Location ID: 306765



Photo 3. View of rill erosion forming in the southern interim reclamation and along the eastern edge of the access road.

Inspection Photos
Location Name: Holman Canyon 2
Location ID: 306765



Photo 4. View of impacted surface material observed at the well head.



Inspection Photos
Location Name: Holman Canyon 2
Location ID: 306765



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of indian ricegrass, juniper and gambel oak.

API #: 067-08720