

**Operator: CIVITAS NORTH LLC**

**Location Name: Hunt 8-60 6C**

**Loc ID: 454166**

**Inspection: 709100215**




Exhibit A




Exhibit B



**Exhibit C**

**CA:** Wellhead sign not properly installed. Comply with Rule 605.d.

**CA Resolution:** Operator has fixed and appropriately installed identified Wellhead signs to comply with Rule 605.d.



**Exhibit A**



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



**Exhibit G**



Exhibit H



Exhibit I



**Exhibit J**



**Exhibit K**

**CA:** Unused equipment (metal pipe, extra signs, spool of tubing, wiring, screws and nuts) observed on location. Comply with Rule 606

**CA Resolution:** Operator has removed identified equipment from the location to comply with Rule 606.

**CA:** Trash observed throughout location and among the wellheads. See photo documentation. Comply with Rule 606

**CA Resolution:** Operator has removed identified trash, debris, and tumbleweeds to comply with Rule 606.