

Interim and Stormwater Inspection

February 15 , 2024

Operator: Crestone Peak Resources Operating- #10633

Location ID: 453474

Inspection Document #: 709400793

Weld County, CO

NWSW Section 25 T1N R66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Sam 3H-25H-M166

Location ID: 453474



Photo 1. Photo taken of location sign, facing east.



Photo 2. Photo taken of wells on site. Photo taken facing southwest.



Inspection Photos
Location Name: Sam 3H-25H-M166
Location ID: 453474



Photo 3. Photo taken of mowed vegetation on topsoil stockpile on well pad. Photo taken facing south.



Photo 4. Photo taken of mowed vegetation on west side of well pad. Photo taken facing north.

Inspection Photos
Location Name: Sam 3H-25H-M166
Location ID: 453474



Photo 5. Photo taken of secondary containment on well pad missing wildlife protection. Photo taken facing east.



Photo 6. Photo taken of tank battery off pad. Photo taken facing northeast.

Inspection Photos
Location Name: Sam 3H-25H-M166
Location ID: 453474



Photo 7. Photo taken of equipment on site from ongoing spill remediation on location. Photo taken facing northwest



Photo 8. Photo taken of mowed vegetation around location. Photo taken facing southeast.

Inspection Photos

Location Name: Sam 3H-25H-M166

Location ID: 453474



Photo 9. Photo taken of potholes lacking proper fencing on perimeter of location. Photo taken facing west.



Photo 10. Photo taken of potholes lacking proper fencing on perimeter of location. Photo taken facing west.

Inspection Photos
Location Name: Sam 3H-25H-M166
Location ID: 453474



Photo 11. Photo taken of open excavation from on going spill remediation on location. Photo taken facing west.



Photo 12. Photo taken of open excavation from on going spill remediation on location. Photo taken facing northwest.

