

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON L04 696

Location ID: 335597

Date: 2/20/2024



Feb 20, 2024 at 11:02:35



Feb 20, 2024 at 11:03:01

Location Entrance – Photo #09377

Wellheads – Photo #09378

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON L04 696

Location ID: 335597

Date: 2/20/2024



Separators – Photo #09379



Tank Battery – Photo #09380

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON L04 696

Location ID: 335597

Date: 2/20/2024



Open-Ended Line on Tank – Photo #09382



Open-ended/Unprotected Tank Vent – Photo #09381