

Inspection Photos

Location Name: SCHMIER-65N64W/32SWSW

Location ID: 331950



Photo #1

Schmier 19-32 (123-21618) Wellsite

Temporarily Abandoned | TA



Photo #2

Schmier 19-32 Wellsite

Temporarily Abandoned | TA

wellsite entrance



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: SCHMIER-65N64W/32SWSW

Location ID: 331950



Photo #3

Schmier 19-32, HSR-Tullberg 13-32 Battery site

Inactive | Shut-down

Formerly served:

HSR-Josh-Hurl 12-32; Plugged & Abandoned | PA

Equipment Documented; Loc ID: 331950



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources