

Inspection Photos

Location Name: HSR-TULLBERG-65N64W/32SWSW

Location ID: 329183



Colorado Energy & Carbon Management Commission
Weld County
+40.349845 -104.580186
355° N
2024-02-21 16:06

Photo #1

HSR-Tullberg 13-32 (123-16976) Wellsite
Temporarily Abandoned | TA



Colorado Energy & Carbon Management Commission
Weld County
+40.349633 -104.580182
340° N
2024-02-21 16:05

Photo #2

HSR-Tullberg 13-32 Wellsite
Temporarily Abandoned | TA
wellsite entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-TULLBERG-65N64W/32SWSW

Location ID: 329183



Photo #3

Schmier 19-32, HSR-Tullberg 13-32 Battery site

Inactive | Shut-down

Formerly served:

HSR-Josh-Hurl 12-32; Plugged & Abandoned | PA

Equipment Documented; Loc ID: 331950



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources