

Inspection Photos

Location Name: SCHMIER-65N64W/32SWSW

Location ID: 331950



Colorado Energy & Carbon Management Commission
Weld County
+40.352075, -104.582824
151° SE
2024-02-21 16:40

Photo #1

Schmier 19-32, HSR-Tullberg 13-32 Battery site

Inactive | Shut-down

Formerly served:

HSR-Josh-Hurl 12-32; Plugged & Abandoned | PA



Colorado Energy & Carbon Management Commission
Weld County
+40.352398, -104.582780
188° S
2024-02-21 16:28

Photo #2

Thistle Down B 31-17 Battery site

Inactive | Shut-down

Battery site entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SCHMIER-65N64W/32SWSW

Location ID: 331950



Photo #3

Schmier 19-32, HSR-Tullberg 13-32 Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

Thistle Down B 31-17 Battery site

Inactive | Shut-down

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SCHMIER-65N64W/32SWSW
Location ID: 331950



Photo #5

Schmier 19-32, HSR-Tullberg 13-32 Battery site

Inactive | Shut-down

Battery sign



Photo #6

Thistle Down B 31-17 Battery site

Inactive | Shut-down

Crude oil tank

CA: NFPA placard missing



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: SCHMIER-65N64W/32SWSW

Location ID: 331950

Associated Wells	API	Status
Schmier 19-32	123-21618	TA
HSR-Tullberg 13-32	123-16976	TA

Photo #7

Schmier 19-32, HSR-Tullberg 13-32 Battery site

Inactive | Shut-down

Associated well(s)

2: Temporarily Abandoned | TA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources