

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2024

Submitted Date:

02/22/2024

Document Number:

707602422**FIELD INSPECTION FORM**Loc ID 331950 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269078	WELL	TA	09/01/2019	OW	123-21618	SCHMIER 19-32	TA

**General Comment:**

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs  
(331950, 329183).

(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location ID  
(329175).

(Well(s): 1: Plugged &amp; Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID  
(Pending).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707602422 and/or Location ID #331950  
for TA Well(s) info.B.) Field Inspection Report doc. #707602424 and/or Location ID #329183  
for TA Well(s) info.C.) Field Inspection Report doc. #707602426 and/or Location ID #329175  
for PA Well(s) info.D.) Field Inspection Report doc. #707602428 and/or Location ID #331950  
for Battery / Facility, Equipment info.

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ casing valve.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.351972,-104.582710
Comment:	Centralized Battery serves 2 Location IDs (331950, 329183). (Well(s): 2: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	269078	Type:	WELL	API Number:	123-21618	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned   TA. Disconnected from flowline. Locked-Out, Tagged-Out   LOTO. OOSLAT applied at well, separator. Blue TA tag posted. CECMC records last production: 05/2019.  Form 4 on file. TA date: 06/13/2019. Approved. DH-CIBP set. Form 21 MIT on file. MIT date: 01/13/2020. Approved. Form 6A on file. Out-of-Svc Designation. Date: 05/22/2019. Approved.</div>							
Corrective Action:							Date:		
BradenHead									
Date of Last Brhd Test:		05/07/2023		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type:			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:							Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On WED 02/21/2024 at approximately 16:00 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: SCHMIER-65N64W/32SWSW Location ID: 331950 Well Name(s): Schmier 19-32. API: 123-21618. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned   TA. Battery: Inactive   Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/22/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602423	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439196">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6439196</a>