

Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 2/21/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest at the beginning of the access road. The road has been widened in this area from trucks onto the road..



Inspection Photos



Photo 2. Facing north along the road. There is vehicle rutting that needs to be repaired and the road needs to be maintained to prevent widening and unnecessary disturbance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 2/21/2024

Inspection Photos



Photo 3. Facing west toward the access road. The side of the road needs to be seeded and stabilized and the road needs to be crowned and graveled if the well is developed. Disturbance needs to be better minimized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 2/21/2024

Inspection Photos



Photo 4. The vehicle ruts that went outside of the road will need to be raked and seeded..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:483886 | Date: 2/21/2024

Inspection Photos



Photo 5. Facing west toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:483886 | Date: 2/21/2024

Inspection Photos



Photo 6. The drill cuttings are not properly stored with containment and have spread off the liner.



Inspection Photos



Photo 7. The containers are filled with drill cuttings and appear to be leaking out from the back gate. The drill cuttings are not properly stored with containment and have spread off the liner.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 2/21/2024

Inspection Photos



Photo 8. Facing toward the soil stock pile. The stock pile will need to be seeded before the growing season unless it will be re-spread for reclamation before that time.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 2/21/2024