

Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Feb 22, 2024 at 12:41:02 PM
CO



Feb 22, 2024 at 12:41:59 PM
CO

Photo # 7457 From entrance to location

Photo # 7458 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Feb 22, 2024 at 12:49:55 PM
CO



Feb 22, 2024 at 12:51:57 PM
CO

Photo # 7459 Location

Photo # 7460 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Photo # 7461 Stored supplies & improperly stored container of unknown chemical



Photo # 7462 Stored supplies & Open container full of unknown fluid/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Photo # 7463 Open container full of unknown fluid/wildlife hazard




Photo # 7464 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975




Photo # 7465 Debris



Photo # 7466 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC DEVER 36-11 (K36) Pad

Location ID: 334975



Photo # 7467 Tank battery lacks required signage