

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 2/20/2024



Location Entrance – Photo #09396



Wellheads – Photo #09398

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 2/20/2024



Separators – Photo #09397



Tank Battery – Photo #09401

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335766

Date: 2/20/2024



Lack of Stabilization – Photo #09403



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09404**