

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON/036B 596

Location ID: 335658

Date: 2/20/2024



Location Entrance – Photo #09421



Wellheads – Photo #09422

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON/036B 596

Location ID: 335658

Date: 2/20/2024



Separators – Photo #09424



Tank Battery – Photo #09425

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON/036B 596

Location ID: 335658

Date: 2/20/2024



Tank Not Labeled – Photo #09426



Open-Ended Vent – Photo #09427