

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL 1-12 (L1B) Pad

Location ID: 334851



Photo # 7414 From entrance to location



Photo # 7415 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL 1-12 (L1B) Pad

Location ID: 334851



Photo # 7416 Location



Photo # 7417 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL 1-12 (L1B) Pad

Location ID: 334851



Photo # 7418 Location



Photo # 7419 Rupture disc vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL 1-12 (L1B) Pad

Location ID: 334851



Photo # 7420 Rupture disc vent line lacks cap



Photo # 7421 Rupture disc vent line lacks cap



Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL 1-12 (L1B) Pad

Location ID: 334851



**Photo # 7422 Methanol chemical label weathered, cracking
& some info becoming illegible.**