

Final Reclamation Inspection

February 22nd, 2024

Operator: Logos Operating LLC - 10679

Location ID: 326440

Inspection Document #: 714000460

La Plata County, CO

Township: NENE 8 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 25A
Location ID: 326440

2/22/24
+37.122998,-107.843714
107° E



Photo 1. View of the disturbance facing center from the entrance.



API #: 067-08100

Inspection Photos
Location Name: Bondad 33-9 25A
Location ID: 326440

2/22/24
+37.122996,-107.843772
74° E



Photo 2. View of southern interim reclamation area facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08100

Inspection Photos

Location Name: Bondad 33-9 25A

Location ID: 326440



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Storm water CA identified in the previous inspection doc #702500563 has been addressed/resolved. No other erosion issues were observed along the access road.

API #: 067-08100

Inspection Photos
Location Name: Bondad 33-9 25A
Location ID: 326440

2/22/24
+37.119353,-107.847904
149° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of grama grass, sagebrush and juniper.

API #: 067-08100