

# Final Reclamation Inspection

February 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 306794

Inspection Document #: 714000461

La Plata County, CO

Township: SWNW 9 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FC Southern Ute Com 005 2  
Location ID: 306794



Photo 1. View of the disturbance facing center from the entrance.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08776

Inspection Photos  
Location Name: FC Southern Ute Com 005 2  
Location ID: 306794

2/22/24  
+37.118982,-107.837969  
19° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the western interim reclamation area facing north.

API #: 067-08776

Inspection Photos  
Location Name: FC Southern Ute Com 005 2  
Location ID: 306794



Photo 3. View of impacted surface material at the muffler.



Inspection Photos

Location Name: FC Southern Ute Com 005 2

Location ID: 306794



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised of intermediate wheatgrass and sagebrush.

API #: 067-08776