

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 1 Location.

Photo 2 Location.

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 3 Location entrance.

Photo 4 Fresh water transport & Axis Cement pump truck.

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 5 WH/BOP.

Photo 6 Axis Cement bulk truck.

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 7 Brigade WO Rig.



Photo 8 Packer out of the hole.