

Inspection Photos

Operator: UTAH GAS CORP -10539

Location Name: DOUGLASS CREEK UNIT #1

Location ID: 314293 API #: 05-103-05083

Inspection Date: 2/23/2024 Inspection Doc#: 693806748



Location overview looking N



Wellhead inside housing



Inspection Photos

Operator: UTAH GAS CORP -10539

Location Name: DOUGLASS CREEK UNIT #1

Location ID: 314293 API #: 05-103-05083

Inspection Date: 2/23/2024 Inspection Doc#: 693806748



Pump housing



Tank battery

Inspection Photos

Operator: UTAH GAS CORP -10539

Location Name: DOUGLASS CREEK UNIT #1

Location ID: 314293 API #: 05-103-05083

Inspection Date: 2/23/2024 Inspection Doc#: 693806748



Separator and Meter housing



Combustor