

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 2/22/2024



**Location Entrance – Photo #09493**



**Wellheads – Photo #09494**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 2/22/2024



Separators – Photo #09496



Tank Battery – Photo #09495



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 2/22/2024



Lack of Stabilization – Photo #09497



Lack of Stabilization – Photo #09498

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 2/22/2024



**Lack of Stabilization – Photo #09501**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09502**