

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Mobil/GM 24-27

Location ID: 335397

Date: 2/22/2024



Location Entrance – Photo #09504



Wellheads – Photo #09505

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Mobil/GM 24-27

Location ID: 335397

Date: 2/22/2024



Separators – Photo #09511



Tank Battery – Photo #09510

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Mobil/GM 24-27

Location ID: 335397

Date: 2/22/2024



Lack of Stabilization – Photo #09506



Lack of Stabilization – Photo #09508

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Mobil/GM 24-27

Location ID: 335397

Date: 2/22/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09513