

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 2/22/2024



Location Entrance – Photo #09515

Wellhead – Photo #09516

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 2/22/2024



Separators – Photo #09520



Tank Battery – Photo #09518

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 2/22/2024



Label Missing Tank Capacity Information – Photo #09519