

Interim Reclamation and Stormwater Inspection

Date: 2/22/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 433642

Inspection Document #: 713900397

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Anschutz Equus Farms

#4-62-9_10 North

Location ID: 433642



Photo 1. The photo was taken at the entrance to the facility along the access road facing West. The photo illustrates the access road has no stormwater issues at this time.

Photo 2. The photo was taken at the entrance to the facility facing Northeast. The photo illustrates the operator sign and warning signage.

Inspection Photos

Location Name: Anschutz Equus Farms

#4-62-9_10 North

Location ID: 433642



Photo 3. The photo was taken at the well location facing East. The photo illustrates interim areas are being managed actively by evidence of mowing.



Photo 4. The photo was taken at the well location facing Northeast. The photo illustrates the boundary of the production pad being stabilized by a gravel berm.

Inspection Photos

Location Name: Anschutz Equus Farms

#4-62-9_10 North

Location ID: 433642



ECMC
288° W
2/22/24, 2:38 PM



ECMC
350° N
2/22/24, 2:41 PM

Photo 5. The photo was taken at the well location facing West. The photo illustrates the retaining wall on the West side of the facility.

Photo 6. The photo was taken at the well location facing North. Refer to the comment for photo 3.



Inspection Photos

Location Name: Anschutz Equus Farms

#4-62-9_10 North

Location ID: 433642



Photo 7. The photo was taken at the well location facing East..
Refer to the comment for photo 3.

Photo 8. The photo was taken at the well location facing East.
Refer to the comment for photo 3.

Inspection Photos

Location Name: Anschutz Equus Farms

#4-62-9_10 North

Location ID: 433642



Photo 9. The photo was taken at the well location facing East. The photo illustrates degraded wattle in the Northeast corner of the facility that now is considered debris.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Number: 713900397

Inspection Photos

Location Name: Anschutz Equus Farms

#4-62-9_10 North

Location ID: 433642



Photo 5. Description



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 713900397