

Inspection Photos
Location Name: Federal Osprey 35-3
Location ID: 331181



Photo 1 – Unused Secondary Containment

Photo 2 – Unused Rods

Inspection Photos
Location Name: Federal Osprey 35-3
Location ID: 331181



Photo 3 – Unused Tubing



Photo 4 – Gas Engine House

Inspection Photos
Location Name: Federal Osprey 35-3
Location ID: 331181



Photo 5 – Unused Pipe and Fencing



Photo 6 – Fencing is in disrepair

Inspection Photos
Location Name: Federal Osprey 35-3
Location ID: 331181



Photo 7 – Wellsite

Photo 8 – Wellhead

Inspection Photos
Location Name: Federal Osprey 35-3
Location ID: 331181



Photo 9 – Unmarked Riser

Photo 10 – Unused Wellhead Parts

Inspection Photos
Location Name: Federal Osprey 35-3
Location ID: 331181



Photo 11 – Well Sign

Photo 12 – Wellsite