

Final Reclamation Inspection

February 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 307029

Inspection Document #: 714000470

La Plata County, CO

Township: NENE 7 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lyle Short A 3
Location ID: 307029

2/22/24
+37.123692,-107.862274
350° N



Photo 1. View of the disturbance facing center from the entrance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09671

Inspection Photos
Location Name: Lyle Short A 3
Location ID: 307029

2/22/24
+37.124009,-107.858267
2° N



Photo 2. View of eastern interim reclamation facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09671

Inspection Photos
Location Name: Lyle Short A 3
Location ID: 307029



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Musk thistle CA identified in the previous inspection doc
#693902801 has been addressed/resolved.

API #: 067-09671

Inspection Photos
Location Name: Lyle Short A 3
Location ID: 307029



2/22/24

+37.124275,-107.858398

298° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of unused oil and gas fencing equipment observed on location.

API #: 067-09671

Inspection Photos
Location Name: Lyle Short A 3
Location ID: 307029



Photo 5. View of weedy russian thistle debris in the northern and western portions of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09671

Inspection Photos
Location Name: Lyle Short A 3
Location ID: 307029

2/22/24
+37.124546,-107.858913
273° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of active pasture reference area.

API #: 067-09671