

Final Reclamation Inspection

February 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 333518

Inspection Document #: 714000471

La Plata County, CO

Township: SWNE 7 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lyle Short A 1
Location ID: 333518

2/22/24
+37.121075,-107.863479
99° E



Photo 1. View of the disturbance facing center from the entrance.



API #: 067-06911

Inspection Photos
Location Name: Lyle Short A 1
Location ID: 333518



Photo 2. Woody debris observed around the well head.



Inspection Photos
Location Name: Lyle Short A 1
Location ID: 333518



Photo 3. View of unused oil and gas equipment observed on location.



Inspection Photos
Location Name: Lyle Short A 1
Location ID: 333518



Photo 4. Weedy kochia debris observed lining the disturbance perimeter fence.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources