

Final Reclamation Inspection

February 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326623

Inspection Document #: 714000472

La Plata County, CO

Township: SESW 7 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Alva Short A 2
Location ID: 326623



2/22/24
+37.114319,-107.867349
309° NW

Photo 1. View of the disturbance facing center from the entrance.



2/22/24
+37.114319,-107.867349
201° S

ALVA SHORT A 2
SIMCOE LLC
ELEVATION: 6449 API #: 05-067-08425 DWR #: 70666-F
NAME OF TRIBE: N/A LEASE TYPE: N/A LEASE #: N/A CA #: N/A
SURFACE LOCATION: 85SW SEC 7 - T33N - R01W 1170' FSL 2490' FWL
BOTTOM HOLE LOCATION: SAME AS SURFACE LOCATION
LATITUDE: 37.11435061 LONGITUDE: -107.8676665
NEAREST ADDRESS: 8150 HWY 580
CONTROL CENTER 24 HR. PHONE #: 970-247-6918
EMERGENCY CONTACT #: 911

Inspection Photos
Location Name: Alva Short A 2
Location ID: 326623



Photo 2. Woody debris observed around active equipment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Alva Short A 2
Location ID: 326623



Photo 3. View of unused oil and gas equipment observed on location.



Inspection Photos
Location Name: Alva Short A 2
Location ID: 326623

2/22/24
+37.114340,-107.867813
341° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Weedy kochia debris observed lining the western edge of the disturbance.

API #: 067-08425

Inspection Photos
Location Name: Alva Short A 2
Location ID: 326623

2/22/24
+37.114719,-107.867697
49° NE

