

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: Sam 25H-M166**

**Loc ID: 453474**

**Inspection: 709400793**



**Exhibit A**

**CA:** Lacking proper fencing around potholes on tank battery perimeter, causing danger or wildlife and human life. Comply with Rule 606.

**CA Resolution:** Operator has reported that fence around sample holes has been repaired to comply with Rule 606.