

Inspection Photos
Location Name: Frank 35-7
Location ID: 332033



Photo 1 – Pumping Unit



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Frank 35-7
Location ID: 332033



Photo 3 – Wellhead appears to have been Cut and Capped



Photo 4 – Unmarked Riser

Inspection Photos
Location Name: Frank 35-7
Location ID: 332033



Photo 5 – Well Sign