

Final Reclamation Inspection

February 22nd, 2024

Operator: Logos Operating LLC - 10679

Location ID: 385356

Inspection Document #: 714000475

La Plata County, CO

Township: NWSE 18 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 23
Location ID: 385356



Photo 1. View of the disturbance facing center from the entrance.



API #: 067-05414



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 23
Location ID: 385356



Photo 2. View debris observed around the well head.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05414

Inspection Photos
Location Name: Bondad 33-9 23
Location ID: 385356

2/22/24
+37.101929,-107.863089
358° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of western interim reclamation area facing north.
Note: weed CA identified in previous inspection doc #693902784
has been addressed/resolved.

API #: 067-05414

Inspection Photos
Location Name: Bondad 33-9 23
Location ID: 385356

2/22/24
+37.101929,-107.863089
85° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of reference area comprised of crested wheatgrass.

API #: 067-05414