

# Final Reclamation Inspection

February 22nd, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 312096

Inspection Document #: 714000476

La Plata County, CO

Township: SWSW 5 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Hayes 33-9 5-3, 3A  
Location ID: 312096

2/22/24  
+37.128918,-107.854174  
143° SE



Photo 1. View of the disturbance facing center from the entrance.





Inspection Photos  
Location Name: Hayes 33-9 5-3, 3A  
Location ID: 312096



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Surface owner equipment CA identified in the previous inspection doc #702500105 has been addressed.

API #: 067-08427, 09429



Inspection Photos

Location Name: Hayes 33-9 5-3, 3A

Location ID: 312096



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Guy line anchor marking CA identified in the previous inspection doc #70250010 has been addressed/resolved.

API #: 067-08427, 09429



# Inspection Photos

Location Name: Hayes 33-9 5-3, 3A

Location ID: 312096



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Impacted surface material observed at both the 5-3 and 5-3A well locations.

API #: 067-08427, 09429