

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2024

Submitted Date:

02/26/2024

Document Number:

696306027

FIELD INSPECTION FORM

Loc ID 468559 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Edwardson, Dylan		dylan.edwardson@state.co.us	
Reed, Shawn		Shawn@strachanexploration.com	
Harms, Jason	303-330-1921	jason@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
332033	LOCATION	AC	03/20/2020		-	FRANK-68N60W 35SWNE	AC

General Comment:

This is a Tank Battery Inspection ONLY

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.611820,-104.052930
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	<input type="text"/>

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 332033 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Location Shut-In at the time of this Inspection.
Well Frank 35-7 API 123-21739 associated with Tank Battery appears to have been Plugged and Abandoned per Form 6S - 403602312 dated 11.20.2023.

Form 271 - 403580290 Submitted on 11.01.2023; Approved on 11.02.2023 for Decommissioning Oil and Gas Facility and Pit Closure on File. No Surface Equipment appears to have been removed yet. Three Months (90 Days) to remove Equipment from Form 27 approval date has passed on 02.02.2024 per Rule 1004.a

Form 27S - 403674331 dated 02.01.2024 has been submitted for Quaterly Update

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width:100%;" type="text"/>						Date: _____
Corrective Action: <input style="width:100%;" type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:		
Reference Point: <u>SE</u>	Other: _____	Length: _____	Width: _____			
Lining:						
Liner Type:		Liner Condition:				
Comment: <input style="width:100%;" type="text"/>						Date: _____
Corrective <input type="checkbox"/>						
Fencing:						
Fencing Type:		Fencing Condition:				
Comment: <input style="width:100%;" type="text"/>						Date: _____
Corrective <input type="checkbox"/>						
Netting:						
Netting Type: <u>Mesh</u>		Netting Condition: <u>Good</u>				
Comment: <input style="width:100%;" type="text"/>						Date: _____
Corrective <input type="checkbox"/>						
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>			
Comment: <input style="width:100%;" type="text"/>						Date: _____
Corrective <input type="checkbox"/>						

COGCC Comments		
Comment	User	Date
<p>On Thursday 02/22/2024 at approximately 12:23 PM, I, Compliance Specialist Erica Petrie, conducted a Field Inspection at Strachan Exploration INC, Frank 35-7 Tank Battery, at Location #468559 in Weld County, Colorado.</p> <p>During this Inspection the following possible Compliance Issues were observed:</p> <p>SI - Location Shut-In at the time of this Inspection. Well Frank 35-7 API 123-21739 associated with Tank Battery appears to have been Plugged and Abandoned per Form 6S - 403602312 dated 11.20.2023.</p> <p>Form 27I - 403580290 Submitted on 11.01.2023; Approved on 11.02.2023 for Decommissioning Oil and Gas Facility and Pit Closure on File. No Surface Equipment appears to have been removed yet. Three Months (90 Days) to remove Equipment from Form 27 approval date has passed on 02.02.2024 per Rule 1004.a</p> <p>Form 27S - 403674331 dated 02.01.2024 has been submitted for Quaterly Update</p> <p>A follow up on this Site Inspection will be conducted to ensure the Compliance Issues have been corrected to comply with ECMC rules.</p>	petrie	02/26/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306028	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6443048