


**Inspection Photos**  
**Location Name: Winters 33-3 Tank Battery**  
**Location ID: 417384**



**Photo 1 Separator house need to be cleaned fire hazard**



**Photo 2**