

Inspection Photos  
Location Name: Khaki Campbell 25-14HN  
Location ID: 45368



Photo 1 – Tank Battery

Photo 2 – Tank Battery

Inspection Photos  
Location Name: Khaki Campbell 25-14HN  
Location ID: 45368



Energy and Carbon Management Commission  
40.6403, -104.26261, 4952.3ft  
02/22/2024 15:11:17



Energy and Carbon Management Commission  
40.64099, -104.26331, 4953.5ft  
02/22/2024 15:06:28

Photo 3 – Tank Battery Sign

Photo 4 – Wellhead

Inspection Photos  
Location Name: Khaki Campbell 25-14HN  
Location ID: 45368



Energy and Carbon Management Commission  
40.64111, -104.26408, 4957.5ft  
02/22/2024 15:06:54



Energy and Carbon Management Commission  
40.64065, -104.26349, 4952.0ft  
02/22/2024 15:07:29

Photo 5 – Gas Injection Meter House

Photo 6 – Separator and Heater Treater

**Inspection Photos**  
**Location Name: Khaki Campbell 25-14HN**  
**Location ID: 45368**



**Photo 7 – Unmarked Riser**

**Photo 8 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Khaki Campbell 25-14HN**  
**Location ID: 45368**



**Photo 9 – Unmarked 1” Riser at Heater Treater**

**Photo 10 – Compressor**

**Inspection Photos**  
**Location Name: Khaki Campbell 25-14HN**  
**Location ID: 45368**



**Photo 11 – Compressor**

**Photo 12 – Gas Meter Houses**

Inspection Photos  
Location Name: Khaki Campbell 25-14HN  
Location ID: 45368



Photo 13 – ECDs

Photo 14 – Unmarked Risers at ECDs

Inspection Photos  
Location Name: Khaki Campbell 25-14HN  
Location ID: 45368



Energy and Carbon Management Commission  
40.64029, -104.26298, 4946.8ft  
02/22/2024 15:11:00



Energy and Carbon Management Commission  
40.63996, -104.26168, 4958.6ft  
02/22/2024 15:13:57

Photo 15 – Condensate Vault

Photo 16 – Sign at Entrance