

Operator: Crestone Peak Resources
Location Name: GEIST MULTI WELL PAD 0-2-32
Loc ID: 331851
Inspection: 715400004



Exhibit A



Exhibit B

CA: Weed debris at wellhead. Comply with Rule 606.

CA Resolution: Weeds have been removed to comply with Rule 606.