

# Interim and Stormwater Inspection

February 15, 2024

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 425469

Inspection Document #: 709400797

Weld County, CO

NWSW Section 28 T1N R66W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MARRS 2N-28HZ  
Location ID: 425469



**Photo 1.** Photo taken of location sign, facing west.



**Photo 2.** Photo taken of well heads. Photo taken facing northwest.



Inspection Photos  
Location Name: Marrs 2N-28HZ  
Location ID: 425469



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing northeast.



**Photo 4.** Photo taken of weeds (kochia & russian thistle) on south side of tank battery pad. Photo taken facing east.

Inspection Photos  
Location Name: Marrs 2N-28HZ  
Location ID: 425469



**Photo 5.** Photo taken of weeds (kochia & russian thistle) on west side of tank battery pad. Photo taken facing north.



**Photo 6.** Photo taken of trash on site. Photo taken facing north.

Inspection Photos  
Location Name: Marrs 2N-28HZ  
Location ID: 425469



**Photo 7.** Photo taken down fencing between well and tank battery pad. Photo taken facing northeast.



**Photo 8.** Photo taken of weeds (kochia & russian thistle) on north side of well pad. Photo taken facing northwest.