

# Interim and Stormwater Inspection

February 12, 2024

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 429708

Inspection Document #: 709400803

Weld County, CO

SWSE Section 10 T2N R65W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Cook 37C-3HZ  
Location ID: 429708



**Photo 1.** Photo taken of location sign, facing north.



**Photo 2.** Photo taken of well heads. Photo taken facing northeast.



Inspection Photos  
Location Name: Cook 37C-3HZ  
Location ID: 429708



**Photo 3.** Photo taken of tank battery on pad. Photo taken facing south.



**Photo 4.** Photo taken of weeds (kochia & russian thistle) on east side of well pad. Photo taken facing east.

Inspection Photos  
Location Name: Cook 37C-3HZ  
Location ID: 429708



**Photo 5.** Photo taken of weeds (kochia & russian thistle) on south side of tank battery pad. Photo taken facing west.



**Photo 6.** Photo taken of weeds (kochia & russian thistle) on south side of tank battery pad. Photo taken facing east.