

# Interim and Stormwater Inspection

February 12, 2023

Operator: GMT Exploration Company LLC - #10243

Location ID: 479191

Inspection Document #: 709400807

Elbert County, CO

NESE Section 22 T6S R65W

Reed Wold  
Reclamation Specialist, COGCC




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Crystal-Ruby pad  
Facility ID: 479191



**Photo 1.** Photo taken of location sign.



**Photo 2.** Photo taken of wellhead on site. Photo taken facing northeast.





Inspection Photos  
Location Name: Crystal-Ruby pad  
Facility ID: 479191



**Photo 3.** Photo taken of tank battery on site. Photo taken facing west.



**Photo 4.** Photo taken of vegetation and weeds (kochia) in topsoil stockpile in interim reclaimed area of well pad. Photo taken facing south.





Inspection Photos  
Location Name: Crystal-Ruby pad  
Facility ID: 479191



**Photo 5.** Photo taken of bare soil on topsoil stockpile in interim reclaimed area of well pad. Photo taken facing north.



**Photo 6.** Photo taken of bare soil on topsoil stockpile in interim reclaimed area of well pad. Photo taken facing southeast.



Inspection Photos  
Location Name: Crystal-Ruby pad  
Facility ID: 479191



**Photo 7.** Photo of vegetation and weeds (kochia) on the west side of site. Photo tank facing north.



**Photo 8.** Photo of weeds (russian thistle & kochia) on the west side of pad. Photo taken facing south.



Inspection Photos  
Location Name: Crystal-Ruby pad  
Facility ID: 479191



**Photo 9.** Photo of vegetation and weeds (kochia) on the west side of site. Photo tank facing south.