

Inspection Photos

Location Name: CAERUS PICEANCE LLC, EDSON & SCHOLL-68S96W/11SESW

Location ID: 324424

Date: 2/26/2024



Location Entrance – Photo #09569



Wellhead – Photo #09570

Inspection Photos


Location Name: CAERUS PICEANCE LLC, EDSON & SCHOLL-68S96W/11SESW

Location ID: 324424

Date: 2/26/2024



Separator/Gas Meter – Photo #09571



Tank Battery/No Battery Sign Posted – Photo #09572