

Inspection Photos  
Location Name: Crossland 1-2  
API Number: 125-07188



1. Well sign at well location.



2. View of wellhead. Note no Bradenhead visible at surface.

**Inspection Photos**  
**Location Name: Crossland 1-2**  
**API Number: 125-07188**



**3. Well location overview.**



**4. Well sign at remote gas meter run location.**

**Inspection Photos**  
**Location Name: Crossland 1-2**  
**API Number: 125-07188**



**5. Gas meter inside meter shed.**



**6. Vertical separator inside separator shed.**

Inspection Photos  
Location Name: Crossland 1-2  
API Number: 125-07188



7. Produced water tank. Note hatch is missing plug.



8. Remote gathering location overview.