

Final Reclamation Inspection

February 26, 2024

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 323083

Inspection Document #: 697505154

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BICKLER-61N68W 34SWNW
Location ID: 323083



Photo 1. Aerial imagery from 2010 during active operations. This imagery was submitted within the Form 4 Final Reclamation Complete Notice.



Inspection Photos
Location Name: BICKLER-61N68W 34SWNW
Location ID: 323083



Photo 2. Aerial imagery from 2022 after plugging and abandonment operations. Imagery illustrates the surface owner has built over portions of the tank battery and well location. This imagery was submitted within the Form 4 Final Reclamation Complete Notice.



Inspection Photos
Location Name: BICKLER-61N68W 34SWNW
Location ID: 323083



Photo 3. Photo taken south of the location, facing North. Photo illustrates location is within a land use change to agricultural practices. All equipment has been removed.

