

WELL SITE INSPECTION FORM



00066717



3 mile from SW corner 13 sec
WELL NAME #1 Harvey Mason
OPERATOR Wytex
LOCATION SW 13-2N 54W
FIELD Xenia

API NUMBER 05 - -
PERMIT NUMBER _____
COUNTY Washington
INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) ☒ DATE 10-5-88 FN _____ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 2-17-60 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES ☒ NO _____ PITS BACKFILLED: YES ☒ NO _____
MATERIAL BURIED: YES _____ NO ☒ NA _____ SITE CLEAN: YES _____ NO ☒
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO ☒

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS Found VHT base & pump base on abandoned
site 1/2 mi. west of Reichstinger lease.

10/22/91 No bond, No company ~~ERF~~ - ERF Fund