

Inspection Photos
Location Name: Neckien 1
Location ID: 319035

Feb 28, 2024 at 11:16:42 AM
40.017542,-104.664978
Veld County
ECMC



Pic 1 Separator

Feb 28, 2024 at 11:16:45 AM
40.017542,-104.664978
Veld County
ECMC



Pic 2 GMR

Inspection Photos
Location Name: Neckien 1
Location ID: 319035



Pic 3 GMR has not been calibrated, no chart available.



Pic 4 gas sales line appears to be in the close position.

Inspection Photos
Location Name: Neckien 1
Location ID: 319035



Pic 5 Tanks



Pic 6 stained soil on location

Inspection Photos
Location Name: Neckien 1
Location ID: 319035



Pic 7 Stained soil



Pic 8 Stained soil

Inspection Photos
Location Name: Neckien 1
Location ID: 319035



Pic 9 unused equipment on location needs to be removed



Pic 10 No wellhead sign on wellhead

Inspection Photos
Location Name: Neckien 1
Location ID: 319035

Feb 28, 2024 at 11:30:56 AM
40.017944,-104.664994
Veld County
ECMC



Pic 11 tank on location needs to be removed, wellsite activities have been completed, no stormwater containment.

Feb 28, 2024 at 11:31:31 AM
40.017869,-104.665148
Veld County
ECMC



Pic 12 bird netting is not in place on open top tank.

Inspection Photos
Location Name: Neckien 1
Location ID: 319035

Feb 28, 2024 at 11:31:57 AM
40.017869,-104.665148
Veld County
ECMC



Pic 13 rig tank, no stormwater containment.

Feb 28, 2024 at 11:32:03 AM
40.017869,-104.665148
Veld County
ECMC



Pic 14 stained soil near tank

Inspection Photos
Location Name: Neckien 1
Location ID: 319035



Pic 15 back of tanks



Pic 16 Back of tank

Inspection Photos
Location Name: Neckien 1
Location ID: 319035

Feb 28, 2024 at 11:37:35 AM
40.017062,-104.664429
Veld County
ECMC



Pic 16 lease road control measure is not maintained, overgrown with vegetation.

Feb 28, 2024 at 11:38:44 AM
40.015504,-104.664444
Veld County
ECMC



Pic 17 lease road control measures are not maintained, overgrown with vegetation.