

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Energy & Carbon Management Commission
40.09532, -104.88396, 4952.5ft, 328°
02/28/2024 12:57:10



Energy & Carbon Management Commission
40.09615, -104.88401, 4953.2ft, 313°
02/28/2024 12:58:07

Photo 1 Location.

Photo 2 Wellsite.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 3 WH sign.

Photo 4 Pump jack.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 5 WH.

Photo 6 Ancillary equip.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 7 Tank Battery location.

Photo 8 TB sign.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 9 Tank Battery.



Photo 10 Stained soil around west crude tank flow line.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668




Photo 11 Stained soil around west crude tank flow line.

Photo 12 Stained soil under center crude tank flow line & debris.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 13 Stained soil under west crude tank flow line.



Photo 14 Flow line manifold.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 15 Horizontal Heated Separator.

Photo 16 Gas Meter Run.

Inspection Photos
Location Name: Suckla Farms Inc. E1
Location ID: 317668



Photo 17 Stained soil by the Gas Meter Run flow line.