

WELL SITE INSPECTION FOR
(DRILLING AND PLUGGING)



99999999



Well Name Miller 4
Operator Kingwood
Location NWNW 12-2N-54
Field Xenia

API Number 05 (121 - 7070)
Permit # _____
County Wash-
Inspector EBB

JAN 30 1997

OIL & GAS CONS. COMM.

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) ☒ Fail(N) _____ Date 9/25/91 ND _____ DG _____ WO _____ PR _____ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes _____ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____
Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____
Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection _____

Comments: _____



Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____