

Inspection Photos

Location Name: CAERUS PICEANCE LLC, COLOHAN-68S96W/4SENE

Location ID: 334150

Date: 2/27/2024



Location Entrance – Photo #09604



Wellheads – Photo #09605

Inspection Photos

Location Name: CAERUS PICEANCE LLC, COLOHAN-68S96W/4SENE

Location ID: 334150

Date: 2/27/2024



Separators – Photo #09606



Tank Battery – Photo #09608



Inspection Photos

Location Name: CAERUS PICEANCE LLC, COLOHAN-68S96W/4SENE

Location ID: 334150

Date: 2/27/2024



Pig Station – Photo #09611



Lack of Stabilization – Photo #09609

Inspection Photos

Location Name: CAERUS PICEANCE LLC, COLOHAN-68S96W/4SENE

Location ID: 334150

Date: 2/27/2024



Lack of Stabilization – Photo #09610



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09612